

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	9-1-17 Reason	for Maintenance: _	Keg Mais	1T & Pump in	ral thurstion
Property Address: <u>20</u>	299 animolf	Ave N P	roperty Owner's Na	me(Searge	Keid
Municipality: Scar	rdea zip.550	7 Property Iden	tification Number:		
Maintenance Permit No	:f2508x8430 M	laintainer Name an	d License No. Smili	e's Sewer Service/L2	2428
Maintenance Performed Tank(s) Pumped Sludge and scum measured		Tank Measurement (must be completed if tanks NOT pumped)			
		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements)				. <u></u> .	
1. Access used to rem	ove septage: Maintenar	nce Hole 🗌 Other (e	nter authorization co	ode)	
 2. Were all covers securely replaced? Ses No 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🖟 No	☐ Yes No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes 🕅 No	☐ Yes 🗗 🗷	
4. How many gallons of septage were removed? Tank #1 500 gal Tank #2 gal Pretreatment tank gal Pump Tank gal gal 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
	: List any troubleshooting	, minor repairs co	Huucleu, talik sale	ety concerns, or our	el coliceriis.
J. Other information	: List any troubleshooting	, minor repairs co	nducteu, tank sare	ety concerns, or our	er concerns.
6. Location of septage). (6	, minor repairs co	Lan	A App	2 kg

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934