

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit m	ust be completed	
prior to performing maintenance activiti					
Date of Maintenance: $8-22$   Reason	for Maintenance:	Ravina			
Property Address: 16011 31st St. Sc	F	Property Owner's Na	ame: Aften M	arina	
Municipality: <u>PK4m</u> ZIP: <u>5500</u>	Property Ide	ntification Number:		_	
Maintenance Permit No: S9279m7992N	Maintainer Name ar	nd License No. Pinky	's Environmental Sew	er Service/ L1673	
Maintenance Performed Tank Measureme			completed if tanks N	OT pumped)	
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage:   Maintenar	nce Hole Other (e	enter authorization co	de)		
2. Were all covers securely replaced?   Yes	□No				
<ol><li>Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structura</li></ol>				ting depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed:	?				
Tank #1 / S 🖎 gal Tank #2	_gal Pretreatmen	t tankga	l Pump Tank	gal	
5. Other information: List any troubleshooting,	minor repairs con	nducted, tank safe			
	,	,			
6. Location of septage disposal:					
Pinky	s Environmental Se	ewer Service Inc			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673