

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety to					
prior to perform	ning maintenance activitie	s and remain on-	site for the duratio	n of the maintenanc	e activity.	
Date of Maintenance: 8-23-17 Reason for Maintenance: Roufine						
Property Address: 150	054 15th St. Sol	utn Pr	operty Owner's Na	me: <u>Kara Mu</u>	Mahy	
the state of the s	zip: <u>5500</u>				_	
Maintenance Permit No	D:X824807987 M	aintainer Name and	d License No. Pinky	's Environmental Sew	er Service/ L1673	
Maintenar	nce Performed	Tank Measi	urement (must be	completed if tanks N	OT pumped)	
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?		Liquid Level of Tank ——— in				
		Sludge Level in Tank in Scum Level in Tank in				
		Sludge + Scum / Liquid Level X 100				
	no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No 						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed					
Tank #1 /oco gal Tank #2gal Pretreatment tankgal Pump Tankgal						
	: List any troubleshooting,					
Tank und	er returning wall,					
-					11	
6. Location of septag	e disposal:					

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673