

Washington

# Pumping Report

Sewer Services Inc.

Lic: 2502

Date Serviced: 12-29-17 Driver: Corey

Type: <u>Residential</u> Commercial
Industrial

Scheduled Maintenance: X Emergency Services: \_\_\_\_\_ Start time: \_\_\_\_\_

Name: Melody Ward Phone: 612-384-6561

Address: 10540 220th St N City: Scandia

Did you measure the accumulation of scum and sludge? Yes \_\_\_\_\_ No, pumped regardless \_\_\_\_\_

	Tank 1	Tank 2	Tank 3	Tank 4	Pretreatment	Pump Tank
Gallons Billed	<u>1,000</u>					
Scum						
Sludge						
% full						
Operating Depth						
Access used	<u>MH</u>					
Depth to lid	<u>Grade</u>					

I \_\_\_\_\_, refuse to allow the removal of the solids and liquids through the maintenance hole. I understand that removal of solids and liquids through other access points is not considered a compliant method of solids removal and does not fulfill the solids removal requirements of Minn. R. 7080.2450 and 7082.0600

Owner's Signature: \_\_\_\_\_

Tank Type - Precast - Block - Concrete - Plastic - Other

Filter: Yes No Type of system: Gravity Trench

Type of waste: Domestic - Holding - Commercial - Industrial - Flammable waste trap

Are tanks operating at designed depth? Yes ~~No~~

Did you observe sewage discharging onto the ground surface? No Yes, \_\_\_\_\_

Pump Size: \_\_\_\_\_ Electrical condition: \_\_\_\_\_

Are all of the covers securely replaced? Yes No, \_\_\_\_\_

Safety concerns: None

Disposal site: Land

Next recommended pumping: 12-29-19 Other: \_\_\_\_\_

Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_