

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

| This section must b | e completed in its entirety | y to constitute a va | alid maintenance p | ermit. This permit | must be complete | |
|---|--|--|--|--|--------------------|--|
| <u>prior</u> to perfo | orming maintenance activi | ities and remain or | n-site for the durat | tion of the maintena | nce activity. | |
| Date of Maintenance | : 8-29-17 Reason | n for Maintenance: | Routine | | | |
| Property Address: \coprod | 520 120th St. | No. | Property Owner's N | lame: Rod R | athburn | |
| Municipality: <u>Still</u> | INVITED ZIP: 550 | S81 Property Ide | entification Number | : | | |
| Maintenance Permit I | No: <u>e9131+8008</u> | Maintainer Name a | nd License No. Pink | ov's Environmental Ca | | |
| | Control of the Contro | That is a second of the second | nd License No. Filik | dy's Environmental Se | wer Service/ L167. | |
| Maintenance Performed | | Tank Mea | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | | Liquid Level of Tank ——— in | | | |
| Sludge and scum measured | | Sludge Level in | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum | | | | |
| \square Yes \square No (if no provide measurements) | | = % Sludge & Sc | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to re | move septage: Maintena | ance Hole Dother | | | | |
| | ecurely replaced? Yes | | enter dutilonization co | ode) | | |
| 3. Is there evidence | of tank leakage from a se aged, cracked, or structur | ptic, holding, preti | reatment or pump tenance hole cove | tank below the operers? Yes No | ating depth or | |
| | Tank | Leaking Out | Leaking In | Cover Damage | | |
| | Septic/Holding Tank #1 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| 4. How many gallons | of septage were removed | ? | | | | |
| Tank #1 /250 | gal Tank #2 | _gal Pretreatment | t tankga | al Pump Tank | gal | |
| Other information | : List any troubleshooting | , minor repairs con | nducted, tank safe | ty concerns, or othe | r concerns. | |
| No markete, | System too old | | | The state of the s | | |
| | | | | | | |
| 6. Location of septage | e disposal: | | at p | | | |
| | | | | | | |

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673