

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <a href="prior">prior</a> to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 8-31-17 Reason for Maintenance: Routile					
Property Address: 1775 Majestic Pines TVL Property Owner's Name: Cindy Garr					
100	9		ification Number:		
Municipality:					
Maintenance Permit No	:08880 S 8323 Ma	aintainer Name and	l License No. <u>Pinky</u>	's Environmental Sev	ver Service/ L16/3
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
<ul> <li>✓ Tank(s) Pumped</li> <li>☐ Sludge and scum measured</li> <li>Do tanks need to be pumped?</li> <li>☐ Yes ☐ No (if no provide measurements)</li> </ul>		Liquid Level of Tank — in			
		Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum / Liquid Level X 100			
		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Maintenance Hole   Other (enter authorization code)					
2. Were all covers securely replaced?   Yes   No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers?   Yes No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal  5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Deep kinks	cannot get to	munhales			
6. Location of septage disposal:					
			Caralina Inc		

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673