

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	$\frac{7/10/17}{}$ Reaso	on for Maintenance:	ROUTINE			
Property Address: 4	1890 KEATS A	WE N.	Property Owner's I	Name: MELUIN	EDEP /	
Municipality: <u>LAK</u>	E ELMO ZIP:55	042 Property Ide	entification Number	r:		
Maintenance Permit N	lo: <u>r9737K6917</u>	Maintainer Name a	nd License No. Mex	ver Sewer Service Inc	// 015	
				yer sewer service, mc.	7 L 9 1 3	
Maintena	nce Performed	Tank Mea	surement (must be	e completed if tanks N	(OT numbed)	
Tank(s) Pumped			Tank Measurement (must be completed if tanks NOT pumped) Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)) = % Studge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: Mainten	ance Hole 🔲 Other (enter authorization c	code)		
	curely replaced? 🛭 Yes					
	of tank leakage from a se ged, cracked, or structu		reatment or pump	tank below the opera	iting depth or	
evidence or dama	gea, crackea, or structu	rally unsound main	tenance hole cove	ers?	5-	
	Tank	Leaking Out	Leaking In	Cover Damage		
		Leaking Out	Leaking In Yes No			
	Tank			Cover Damage		
	Tank Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	Cover Damage Ves No		
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	Cover Damage Yes No Yes No		
4. How many gallons of Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	Cover Damage Yes No Yes No Yes No Yes No		
Tank #1 <u>/5のひ</u>	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ Pretreatment	Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
Tank #1 <u>/5のひ</u>	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ Pretreatment	Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
Tank #1 <u>/ Soo</u> 5. Other information:	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 List any troubleshooting	☐ Yes ☐ No ☐ Yes ☐ Pretreatment	Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
Tank #1 <u>/5のひ</u>	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 List any troubleshooting	☐ Yes ☐ No ☐ Yes ☐ Pretreatment	Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162