## SSTS MAINTENANCE REPORT

Date of Maintenance 10-19-17 Reason for Maintenance: Maintenance				
Property Address: 21154	Property Owner's Name: Mark Paul			
Municipality: Scandia State MV Zip Code S5073GEO Code/Property I.D. #:				
What was done to the system?	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured.	Liquid Level of Tan	k in. Sludge L	evel in. Scum Level	in. 
Do tanks need to be pumped?  Yes No (If no provide measurements)	Total (Sludge + Scu	um) / Liquid Lev		
* Tank must be pumped if this value is greater than 25%.				
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain				
Explanation:	8		ļ	
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:				
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance				
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.				
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit  Tank#1 Yes Verificatio Method Used:				
Tank#2 Tes You Verificatio Method Used:				
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes No	
Septic/Holding Tank #2	Yes No	☐ Yes 💢 No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes 🕅 No	☐ Yes No	☐ Yes No	
6. How many gallons of septage were removed?				
Tank #1 1000 Tank #2 1000 Pretreatment Tank Pump Tank				
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.				
8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.				

Maintainer's Name: Hassle Free Septic Maintainer's Address: P.O. Box 702 North Branch, MN 55056