DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance	10-6-15 Reason for	Maintenance: Ro	sectine		
Property Address:	380 103rd St	Property	Owner's Name:	regg Anderson	
Municipality: 5+1	hoater si	Zip Code	GEO C	Code/Property I.D. #:	
What was done to the system?		Tank Measurements (must be completed if tanks NOT pumped)			
 ☑ Tank(s) Pumped ☐ Sludge and scum measured. Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurements) 		Liquid Level of Tank Total (Sludge + Scum	in. Sludge) / Liquid L	evel = % Sludge & Scum	in. *
1. Access used to remov	ve septage: 🔲 Maintenar	ice Hole Other (Go	to #3 below)	 Tank must be pumped if th is greater than 25%. 	is value
2. If maintenance hole w	vas used, were all covers se	ecurely replaced?	'es No <i>please ex</i>		
Explanation:					
	illow a Subsurface Sewag sign the following staten		SSTS) to be pumped	l through the maintenance hole,	have
J, , , , , , , , , , , , , , , , , , ,	(own	er's name), refuse to all	ow the removal of so	olids and liquids through the maint	enance
hole. I understand th	at removal of solids and lic	uids through other acc	ess points is not con	sidered maintenance.	
4. Is the tank designed a	as a leaky tank? example: se	epage pit, cesspool, dryv	well, leaching pit		
Tank#1 ☐ Yes ☐	No Verificatio Method U	sed:			
Tank#2 Yes	No Verificatio Method U	sed:			4
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
damaged, cracked, c	Tank	Leaking Out	Leaking In	Cover Damage	
Septi	ic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septi	ic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretr	eatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pum	p Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons of	of septage were removed	?			
Tank #1 _ / 500 Tank #2		Pretreatment Tank Pretreatment Tank		Pump Tank	
7. Other information:	List any troubleshooting	, minor repairs condu	cted, tank safety co	ncerns, or other concerns.	
8. Certification: I here and n	eby certify as a State of Min nade the observations, or o	directly supervised othe	ers in the performanc	e of this job.	
Maintainer's Name:	PINKY'S SEWER SERVICE	Maintainer 	's Address: P.O. Box 3	554 Afton, MN 55001	
Maintainer's License	#: 1673 Maintain	er's Phone #: 651-439-	4847		
Maintainer's Signature A China Date: 10-6-15					