

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entir	ety to constitute a val	id maintenance pe	ermit. This permit m	nust be completed	
prior to performing maintenance acc	tivities and remain on-	site for the durati	on of the maintenan	ce activity.	
	ason for Maintenance: _				
Property Address: 498 WILO Co	MON OF P	roperty Owner's N	ame: Soseph s	5 De Torre	
	S129 Property Ider			- Stocioone	
Maintenance Permit No: <u>Kbプイン チ਼੦੧ੑ०</u>	<u>)</u> Maintainer Name an	d License No.			
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped Liquid Level of Tank					
☐ Sludge and scum measured	Sludge Level in <sup>-</sup>	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 259				if 25% or greater	
<ol> <li>Were all covers securely replaced? </li> <li>Is there evidence of tank leakage from a evidence of damaged, cracked, or structure.</li> </ol>	a septic, holding, pretr	eatment or pump tenance hole cove	tank below the oper	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes 🛛 No	☐ Yes ☒No	☐ Yes ⊠No		
Septic/Holding Tank #2	☐ Yes ☐ No	$\square$ Yes $\square$ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remo	oved?				
Tank #1 $1200$ gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information: List any troubleshoo	oting, minor repairs co	nducted, tank safe	ety concerns, or other	er concerns.	