

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

06

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit i	nust be completed	
<u>prior</u> to perfor	ming majntenance activi	ties and remain on	-site for the durat	ion of the maintena	nce activity.	
Date of Maintenance:	8 11/17 Reason	for Maintenance:	INSPEC	tion		
					0 1	
	0150 Milita		Property Owner's N	ame: 1sey Co	m Baul	
Municipality: WOO	aburg zip:	Property Idea	ntification Number:			
Maintenance Permit N	o: <u>J642378251</u>	Maintainer Name ar	nd License No. $\frac{5c}{}$	Hlonks Sar	. 2989	
	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
2 2 2	- and word	950	Sludge Level in Tank in Scum Level in Tank in			
☐ Sludge and scum n Do tanks need to			.evel X 100			
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater						
□ 163 □ 110 (II	no provide measurements,	- % Staage a see		mis mase se pampea	20% or 5. earer	
1. Access used to ren	nove septage: 🗌 Maintena	ance Hole \square Other (e	enter authorization c	ode)		
2. Were all covers se	curely replaced? 🗌 Yes	□No				
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	d?				
Tank #1	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting	— g, minor repairs co	nducted, tank safe	ety concerns, or oth	er concerns.	
$\bigwedge o$	n complian	L 5.	egin -	Cersjou		
34	City sew	•	6 moths			
6. Location of septage	e disposal:	<u>-</u> E S	Metro			