

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	ety to constitute a van	a maintenance pe	rmit. This permit m	ust be completed	
prior to performing maintenance acti	vities and remain on-	site for the duration	on of the maintenan	ce activity.	
Date of Maintenance: $8-79-17$ Reas	on for Maintenance: _			3. T	
Property Address: 16790 2nd St. N	. Pi	roperty Owner's Na	ame: Walter R	Cobbins	
Municipality: Lakeland Shores ZIP:SS	60√3 Property Iden	tification Number:			
Maintenance Permit No: 18818 w 8228	_ Maintainer Name an	d License No. <u>Sch</u>	Ilomka 29	89	
Maintenance Performed		<u> </u>	completed if tanks h		
Tank(s) Pumped		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in			
☐ Sludge and scum measured		Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measuremen	1(S) = % Studge & Sco	iiii iai	iks must be pumped	11 25% 51 g. 54.54	
1. Access used to remove septage: Maint	enance Hole $\Box$ Other (e	enter authorization co	ode)		
2. Were all covers securely replaced? 📈 Y	'es □ No				
AN 174		eatment or numn	to the balance Alba anas		
3. Is there evidence of tank leakage from a evidence of damaged, cracked, or structure.	septic, nolding, pretr cturally unsound main	tenance hole cove	rs?	ating depth or	
3. Is there evidence of tank leakage from a evidence of damaged, cracked, or structure.  Tank	septic, notding, pretr cturally unsound main  Leaking Out	tenance hole cove	cover Damage	ating depth or	
evidence of damaged, cracked, or struc	cturally unsound main	Leaking In	Cover Damage	ating depth or	
evidence of damaged, cracked, or struc Tank	turally unsound main  Leaking Out	Leaking In	Cover Damage	ating depth or	
evidence of damaged, cracked, or struc  Tank  Septic/Holding Tank #1	Leaking Out    Yes \ No	Leaking In  Ves No	Cover Damage  Yes No	ating depth or	
evidence of damaged, cracked, or structure.  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2	Leaking Out  Yes No	Leaking In  Yes No	Cover Damage  Yes No	ating depth or	
evidence of damaged, cracked, or struct  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank	Leaking Out  Yes No Yes No Yes No	Leaking In  Yes No  Yes No  Yes No	Cover Damage  Yes No Yes No Yes No	ating depth or	
evidence of damaged, cracked, or struct  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank	Leaking Out  Yes No Yes No Yes No Yes No Yes No Res No Res No Res Res	Leaking In  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Pes No	gal	