

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	11-(-17 Reason					
Property Address:	1575 Osgood Ave	F	roperty Owner's N	lame: Dave B	Sindert	
Municipality: Stillu	vater zip: 550	フ82 Property Idea	ntification Number	:		
Maintenance Permit N	0: 2797/9507	Maintainer Name ar	nd License No. Smil	lie's Sewer Service/L	 242 8	
	J		.aeese 7.01 <u>.51111</u>	110 5 50 110 1 50 1 1 1 00 1 E		
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
► Tank(s) Pumped □ Sludge and scum measured Do tanks need to be pumped?		Liquid Level of	Liquid Level of Tank in			
			Sludge Level in Tank in Scum Level in Tank in			
		_	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if i	no provide measurements) = % Studge & SCI	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: Maintena	ance Hole 🗆 Other (e	enter authorization c	ode)	, , , , , , , , , , , , , , , , , , ,	
	, ,			,		
 Were all covers securely replaced? ✓ Yes □ No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? □ Yes ☒ No 						
evidence of dums				•		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🗹 No	☐ Yes 🄼 No	☐ Yes 🄀 No		
	Septic/Holding Tank #2	☐ Yes 🌠 No	☐ Yes 🕅 No	☐ Yes 🏿 No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
••						
	of septage were removed					
	_ gal Tank #2 <u>1006</u>					
o. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank sare	ery concerns, or oth	er concerns.	
			1 6 1	***************************************		
6. Location of septage		Land.	Applical		•	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934