

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity

<u>prior</u> to perior	ming maintenance activiti	es and remain on	-site for the durat	ion of the maintena	ince activity.
Date of Maintenance:	//-,22-/7 Reason f	or Maintenance:	Cleaning		
Property Address:	2601 62nd St	F	ر Property Owner's N	lame: Carolyn E	Miot
4 .	water ZIP: 5505		ntification Number	:	
	0: 5737049964 M				 2428
					
Maintena	nce Performed	Tank Meas	surement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped Sludge and scum measured		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: Maintenan	ce Hole \square Other (ϵ	enter authorization co	ode)	
2 Were all covers se	curely replaced? Yes	¬No			
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐No	☐ Yes ੴNo	☐ Yes ☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1_);000	of septage were removed? _ gal Tank #2 <u>1,000</u> : List any troubleshooting,				
6. Location of septage	disposal:				

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073 License# 2428 P: 651-433-3934