

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	11-7-17 Reason f	or Maintenance:	Rostine	and of the mantene	area delivity.
Property Address:				Name: Mark	Berns
Municipality: Still	1		ntification Numbe	-	
	o: <u>U3867f9846</u> M				_2428
Maintena	nce Performed	Tank Mea	surement (must b	e completed if tanks	NOT pumped)
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes \(\sum \) No (if no provide measurements)		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes XNo	☐ Yes No	☐ Yes 🏋No	
	Septic/Holding Tank #2	☐ Yes 🎾 No	· _	☐ Yes 🄼No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes 🎏 No	☐ Yes 🔀 No	☐ Yes 🖾 No	
Tank #1 <i>1000</i>	of septage were removed? gal Tank #2 <u>1000</u> List any troubleshooting, I	minor repairs co	nducted, tank safe		
6. Location of septage disposal:		1 Wetro	Weiste		

Smilie's Sewer Service
PO BOX 100
Scandia, MN 55073
License# 2428 P: 651-433-3934