

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

		n for Maintenance:	(A(CEN/2)			
Property Address: $\int_{-\infty}^{\infty}$	7488 Keystone	Aue F	Property Owner's N	lame: Jon 1	Cohler	
Municipality: <u> </u>	უ0 ZIP: <u>55</u> 6	038 Property Ide	ntification Number	:		
	10: 5/929; 9841					
Maintena	ince Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
		Liquid Level of Tank in				
Tank(s) Pumped			Sludge Level in Tank in Scum Level in Tank in			
□ Sludge and scum measured Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
	no provide measurements)	= % Sludge & Sci		nks must be pumped		
□ 1€3 □ 140 (II	no provide measurements,	<u>'</u>				
1. Access used to rea	nove septage: 🖾 Maintena	ance Hole \square Other (e	enter authorization co	ode)		
2. Were all covers se	curely replaced? Yes	□No				
	of tank leakage from a se		eatment or pump	tank below the ope	rating depth or	
	aged, cracked, or structu					
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1					
	Separational ing rank in 2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	Yes ☐NoYes ☐No	☐ Yes ☐No☐ Yes ☐No	☐ Yes ☐No		
	Septic/Holding Tank #2	☐ Yes ੴNo	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☐ No☐ Yes ☐ Ho	☐ Yes ☐ No	☐ Yes ☐ No		
• • •	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ Ho ☐ Yes ☐ Ho	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☐ 1√10	<i>⊙</i> gal	
Tank #1 <u>1,000</u>	Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐No☐ Yes ☐No☐ Yes ☐No☐ Yes ☐No☐ Yes ☐No☐		
Tank #1 <u>1,000</u>	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐No☐ Yes ☐No☐ Yes ☐No☐ Yes ☐No☐ Yes ☐No☐		
Tank #1 <u>1,000</u>	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐No☐ Yes ☐No☐ Yes ☐No☐ Yes ☐No☐ Yes ☐No☐		

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073

License# 2428 P: 651-433-3934