

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	11-3-17 Reason f	or Maintenance: _	Rea Mail	ot	
Property Address: 1/540 Lansing Ave / Property Owner's Name: Joel Taverna					
Municipality: 5+7/	1 /		tification Number:	1	
· GOTT LOT. I					
Maintenance Permit No	D: <u>V101221 /31</u> 1 M	amcamer Name an	d License No. 3iiid	le 3 Jewel Jelvice/L	2420
		1			
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Scum / Equid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
\square Yes \square No (if no provide measurements)					
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? ☐ Yes ☐ No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes Who					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐No	☐ Yes ☑No	
	Septic/Holding Tank #2	☐ Yes ♠No	☐ Yes 🖾 No	☐ Yes ☐No	9
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Maria de la companio		1		2/	
6. Location of septage disposal: Mach Colland The					

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934