

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: Property Address:	199 ST Croix	· Cum	roperty Owner's Na	me: Nichae	1 OPhelan
Municipality: <u>SY/</u> Maintenance Permit No	115158x 9862	<u>O</u> ∕ ≮roperty Ider Maintainer Name an			2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes No (if no provide measurements)		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see 3. Is there evidence of	curely replaced? Waintena curely replaced? Yes of tank leakage from a sep ged, cracked, or structur	□ No otic, holding, pretr ally unsound main	eatment or pump tenance hole cove	tank below the ope rs? ☐ Yes 望No	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐No☐	☐ Yes ☐No☐ Yes ☐No	☐ Yes ☑No☐ Yes ⓓNo	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes Z No	☐ Yes Д No	☐ Yes ☐ No	
					•

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934