

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site-for the duration of the maintenance activity.

Date of Maintenance:	//- 7 - / 7 Reason	for Maintenance: _		lais T	
Property Address: 21	985 Parrish	Ra N P	roperty Owner's Na	ame: Lick + Kar	+ Rierman
Municipality: Scan	deh zip: 550	773 Property Iden	tification Number:		
Maintenance Permit No	: K7067c 98481	≻ Maintainer Name an	d License No. Smili	ie's Sewer Service/L	2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
<ul> <li>□ Tank(s) Pumped</li> <li>□ Sludge and scum measured</li> <li>□ Do tanks need to be pumped?</li> <li>□ Yes □ No (if no provide measurements)</li> </ul>		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintena	nce Hole $\Box$ Other (e	nter authorization co	ode)	
3. Is there evidence o	urely replaced? Ves f tank leakage from a sep ged, cracked, or structur	otic, holding, pretr			rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ♠No	☐ Yes 🗗 No	
	Septic/Holding Tank #2	☐ Yes 🗹 No	☐ Yes 🖟 No	□ Yes 🖟 No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ Mo	☐ Yes 🛂 No	
Tank #1 1600	of septage were removed gal Tank #2 1000 List any troubleshooting disposal:	gal Pretreatment	tankg nducted, tank safe	al Pump Tank <u>So</u> ety concerns, or oth	gal er concerns.

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934