

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	11-13-17 Reason	for Maintenance:	Keg Mo	abt		
Property Address: 6	520 177th S	TN	Property Owner's N	lame: Billy Na	ner Kleir	
Municipality: Hu	00 zip:550	Property Ide	ntification Number	ï	/	
Maintenance Permit N	10: +740 n9870	Maintainer Name a	nd License No. <u>Smi</u>	lie's Sewer Service/I	 L2428	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		= % Sludge & Sc	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
\square Yes \square No (if no provide measurements)						
1. Access used to ren	n ove septage : Maintena	nce Hole 🗌 Other (enter authorization c	ode)		
2. Were all covers se	curely replaced? Yes	□No				
	of tank leakage from a sep		reatment or pump	tank below the ope	erating depth or	
evidence of dama	aged, cracked, or structur	ally unsound main	tenance hole cove	ers? 🗌 Yes 🗷 No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 /500	of septage were removed gal Tank #2 List any troubleshooting	_ gal Pretreatmen				
6. Location of septage	disposal:	156 C	o la	and Ap	soly	

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934