

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

And the Control of th	No: <u>137559</u> 9863			completed if tanks	
 ☐ Tank(s) Pumped ☐ Sludge and scum measured ☐ Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements) 		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	nove septage: 📈 Mainten	ance Hole \square Other (enter authorization c	ode)	
22	_				
2. Were all covers se	curely replaced? 🎏 Yes	□ No			
3. Is there evidence	of tank leakage from a se aged, cracked, or structu	ptic, holding, pret			erating depth or
3. Is there evidence	of tank leakage from a se	ptic, holding, pret			erating depth or
3. Is there evidence	of tank leakage from a se aged, cracked, or structu	ptic, holding, pret rally unsound mair	Leaking In	Cover Damage	erating depth or
3. Is there evidence	of tank leakage from a se aged, cracked, or structu Tank	ptic, holding, pret rally unsound mair Leaking Out	Leaking In	Cover Damage	erating depth or
3. Is there evidence	of tank leakage from a se aged, cracked, or structu Tank Septic/Holding Tank#1	Leaking Out Yes No	Leaking In Yes Mo	Cover Damage Yes No	erating depth or
3. Is there evidence	of tank leakage from a seaged, cracked, or structu Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No	erating depth or

Smilie's Sewer Service
PO BOX 100
Scandia, MN 55073
License# 2428 P: 651-433-3934