

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

Dartine

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	11-8-17 Reason	for Maintenance: _	Routine		
Property Address:	1787 Ostrum To	~ l N P	roperty Owner's Na	ame: Carol R	eynolds
Aunicipality Mar	Ne 710:5504	7 Property Iden	tification Number:		
Maintenance Permit No	17383 c9520 N	 Maintainer Name an	d License No. <u>Smili</u>	e's Sewer Service/L	2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
<ul><li>✓ Tank(s) Pumped</li><li>☐ Sludge and scum m</li><li>Do tanks need to b</li><li>☐ Yes ☐ No (if r</li></ul>		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
<ul><li>2. Were all covers sec</li><li>3. Is there evidence of</li></ul>	ove septage: Amaintenal curely replaced? A Yes of tank leakage from a sep ged, cracked, or structur	□ No otic, holding, preti	eatment or pump	tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🏿 No	☐ Yes 🎗 No	☐ Yes 🖾 No	
	Septic/Holding Tank #2	☐ Yes 🄀 No	☐ Yes 🏿 No	☐ Yes KNo	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes 🎗 No	☐ Yes 🏚 No	☐ Yes 🄀 No	
Tank #1_1200	of septage were removed gal Tank #2 1700 : List any troubleshooting	_ gal Pretreatmen	nducted, tank safe	al Pump Tank <u>30</u> ety concerns, or oth	gal ner concerns.

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934