

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Municipality: Sca	2080 238 4 St ndla zip: 550 o: 5/992 b/0232	773 Property Ide	Property Owner's N	:	Andersor
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
 ▼ Tank(s) Pumped □ Sludge and scum measured □ Do tanks need to be pumped? □ Yes □ No (if no provide measurements) 		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see 3. Is there evidence	nove septage: Amaintena curely replaced? Yes of tank leakage from a sep aged, cracked, or structur	□ No otic, holding, preto ally unsound main	reatment or pump tenance hole cove	tank below the ope ers?	erating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🄀 No	☐ Yes 🕱 No	☐ Yes 🏞No	^
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1_1500	of septage were removed _ gal Tank #2 : List any troubleshooting	_ gal Pretreatmen			

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073

License# 2428 P: 651-433-3934