

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: $1/-22-17$ Reason f	or maintenance	Creaning .		
Property Address: 2036/ Ostrum A	ν <u>ε</u> Ε	roperty Owner's N	ame: Jeff	Nelson
Municipality: Scendia ZIP: 5507	<u>3</u> Property Ide	ntification Number:		
Maintenance Permit No: <u>ト み911 と 9963</u> M	aintainer Name ar	nd License No. Smil	ie's Sewer Service/	L2428
<u> </u>				
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	s NOT pumped)
Tank(s) Pumped	Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100			
☐ Sludge and scum measured				
Do tanks need to be pumped?			nks must be pumped	
Yes No (if no provide measurements)				
1. Access used to remove septage:   Maintenan	ce Hole 🗌 Other (e	enter authorization co	ode)	
2. Were all covers securely replaced?	□No			
3. Is there evidence of tank leakage from a sept		eatment or pump	tank below the ope	erating depth or
evidence of damaged, cracked, or structurally unsound maintenance hole covers? $\Box$ Yes $\Box$ No				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐•No	
				_
Septic/Holding Tank #2	☐ Yes ☐No	☐ Yes ☐No	☐ Yes ☐ No	-
Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
		. <u></u>		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	-
Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?	☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ Ho	☐ Yes ☐ No	
Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ Ho	☐ Yes ☐ No	20 gal
Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?	☐ Yes ☐ No ☐ Yes ☐ No ☐ gal Pretreatment	☐ Yes ☐ No☐ Yes ☐ Ho☐	☐ Yes ☐ No☐ Yes ☑ No☐ Yes ☑ No☐ Al Pump Tank 30	
Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?  Tank #1	☐ Yes ☐ No ☐ Yes ☐ No ☐ gal Pretreatment	☐ Yes ☐ No☐ Yes ☐ Ho☐	☐ Yes ☐ No☐ Yes ☑ No☐ Yes ☑ No☐ Al Pump Tank 30	

Smilie's Sewer Service
PO BOX 100
Scandia, MN 55073
License# 2428 P: 651-433-3934