

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: /	<u>// -// -/ 7</u> Reasor	n for Maintenance: 🗸	Reg Mai	<i>b</i> -	· · · · ·
Property Address: 1	699 Hilo.	Ave p	roperty Owner's Na	ame: Brett	Kostuch
Municipality:	zip: <u>55</u>	Property Iden	tification Number:		
Maintenance Permit No	: 4 406Zm938	Maintainer Name an	d License No. <u>Smili</u>	e's Sewer Service/L	2428
	į ,				
Maintenar	ce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Topka Dumped			ank in		
☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped?		Sludge Level in Tank in Scum Level in Tank in			
			Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater		
☐ Yes ☐ No (if r	no provide measurements) Staage a see	<u></u>		
1. Access used to rem	nove septage: Mainten	ance Hole 🗌 Other (e	enter authorization co	ode)	
3. Is there evidence of	curely replaced? A Yes of tank leakage from a se ged, cracked, or structu	eptic, holding, pretr	reatment or pump	tank below the ope	rating depth or
evidence of dama	gen, cracked, or structu	Hally ulisound main	feliatice tiole cove	152 TE 140	
CYICCIICC OI GOIIIG		<u></u>			
evidence of dame	Tank	Leaking Out	Leaking In	Cover Damage	
cyldence of dame	<u> </u>	<u></u>			
Cyldenee of dame	Tank	Leaking Out	Leaking In	Cover Damage	
Cyldenee of dame	Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking in Yes No	Cover Damage Ves Alo	
Cyldenee of dame	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No	
Cyldenee of dame	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No	Leaking in Yes No Yes No Yes No	Cover Damage Yes No Yes No	
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No	Leaking in Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking in Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking in Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal ner concerns.
4. How many gallons Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2 List any troubleshooting	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking in Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal ner concerns.
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2 List any troubleshooting	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking in Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal ner concerns.

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934