

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	<u>/0-24-12</u> Reason	for Maintenance:	Reg M	nin //	ump Fail	
Property Address:	244 Neal A	<u>че</u> Р	roperty Owner's Na	ame: Lee ]	ohnson	
Municipality:	Mater IIP.550	Property Ider				
· · · · — — — — — — — — — — — — — — — —	o:X1693n9523	—— Maintainer Name an	d License No. Smili	ie's Sewer Service/	<u>L2428</u>	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tank	s NOT pumped)	
Tank(s) Pumped			Liquid Level of Tank in			
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to I	1 1	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if						
1. Access used to ren	nove septage: Mainten	ance Hole 🗌 Other (e	enter authorization co	ode)		
<ul> <li>2. Were all covers securely replaced? Yes \( \sum \text{No} \)</li> <li>3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? \( \sum \text{Yes} \)</li> </ul>						
evidence of dama	aged, cracked, or structu	rally unsound main	tenance noie cove	ers: U Yes Mo	, 	
	Tank	Leaking Out	Leaking In	Cover Damage	_	
	Septic/Holding Tank #1	☐ Yes ☐No	□ Yes □ No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes 🗖 No	☐ Yes ☐ Ho	☐ Yes ☐No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	,	
	Pump Tank	☐ Yes No	☐ Yes ( No	☐ Yes ☐ No		
4. How many gallons of septage were removed?  Tank #1 1500 gal Tank #2 1500 gal Pretreatment tank gal Pump Tank 1000 gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
6. Location of septage disposal: Nash Co Law Tark						
6. Location or septag	e disposati. V V V V			- 4		

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934