

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance	e: <u>11-7-17</u> Reason	n for Maintenance:	Ructon	e		
Property Address: _	3765 Briarwood	Aue 1	Property Owner's N	lame: Craig	Campbell	
Municipality: Mah	tomedi zip: 551	N.S Property Ide	ntification Number	:		
	No: <u>U3113</u> 09847				_2428	
<u> </u>		· ·				
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in			
		-				
Sludge and scum measured Do tanks need to be pumped?		11	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Mainten	ance Hole 🗌 Other (	enter authorization c	ode)		
3. Is there evidence	securely replaced? 🄀 Yes e of tank leakage from a se maged, cracked, or structu	ptic, holding, pret		-	erating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🗖 No	☐ Yes 🌠 No	☐ Yes ☑ No		
·	Septic/Holding Tank #2	☐ Yes 🎞 No	☐ Yes ☒No	☐ Yes 🔀 No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1_ <i>1000</i>	ns of septage were removed gal Tank #2 <u>/000</u> on: List any troubleshooting	gal Pretreatmen				
		letro Wa				
6. Location of septa	no dienocal· / VI	マンロフ しんノバスし	51			

Smilie's Sewer Service
PO BOX 100
Scandia, MN 55073
License# 2428 P: 651-433-3934