

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

11044411			W No Trust for Days.		arage.	
Mainten	ance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
✓ Tank(s) Pumped☐ Sludge and scum measuredDo tanks need to be pumped?		II -	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
		ii =				
	no provide measurements	= % Sludge & Sc	ım Ta	nks must be pumped i	f 25% or greater	
1. Access used to re	move septage: Mainten	ance Hole 🗌 Other (enter authorization c	ode)	_	
2. Were all covers se	ecurely replaced? 🔀 Yes	; □ No				
3. Is there evidence	ecurely replaced? 🎏 Yes of tank leakage from a se	eptic, holding, preti			ating depth or	
3. Is there evidence	•	eptic, holding, preti			ating depth or	
3. Is there evidence	of tank leakage from a se	eptic, holding, preti			ating depth or	
3. Is there evidence	of tank leakage from a se aged, cracked, or structu	eptic, holding, preto rally unsound main	tenance hole cove	ers? Yes No	ating depth or	
3. Is there evidence	of tank leakage from a se naged, cracked, or structu Tank	eptic, holding, preto rally unsound main Leaking Out	tenance hole cove	Cover Damage	ating depth or	
3. Is there evidence	of tank leakage from a se naged, cracked, or structu Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes No Yes No	ating depth or	
3. Is there evidence	of tank leakage from a sepaged, cracked, or structure. Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes No Yes No Yes No	ating depth or	
3. Is there evidence	Tank Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	ating depth or	
3. Is there evidence evidence of dam 4. How many gallons	Tank Septic/Holding Tank #2 Pretreatment Tank	eptic, holding, pretorically unsound main Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No		

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073

License# 2428 P: 651-433-3934