

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	12-1-17 Reaso	n for Maintenance:	Routine	·	
Property Address:	1416 132 d St,	<u>v</u>	Property Owner's N	lame: Dean a R	osalve Stel
Municipality: Hvq	0 ZIP:631	[0] Property Ide	ntification Number	•	
Maintenance Permit 1	No: x 8667 110003	Maintainer Name a	nd License No. Smi	lie's Sewer Service/	L2428
Maintena	ance Performed		of the tax devotes a	completed if tank	s NOT pumped)
Tank(s) Pumped Sludge and scum i Do tanks need to  Yes No (if		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	ecurely replaced? Yes of tank leakage from a se aged, cracked, or structu Tank	eptic, holding, preto rally unsound main	tenance hole cove	ers? 🗌 Yes 🔀 No	erating depth or
	Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage	-
		☐ Yes ☑ No	∐ Yes I <b>X</b> ¥No	☐ Yes 🏋 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	·
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1_1 <u>700</u>	of septage were remove gal Tank #2 : List any troubleshooting	gal Pretreatment			
6. Location of septage			p lied	ey concerns, or ou	er concerns.

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073 License# 2428 P: 651-433-3934