

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance	: 12-12-17 Reason f	for Maintenance:			
Property Address:	12701 182 nd st N	<u>/</u>	Property Owner's Na	ame: <u>Clavence</u>	Hemz
Municipality: Ma	rine zip:550°	17 Property Ide	ntification Number:		
Maintenance Permit	No: L7710 f10251 M	aintainer Name ar	nd License No. <u>Smili</u>	e's Sewer Service/L24	128
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped) Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?					
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sci	ım Tan	iks must be pumped if	25% or greater
2. Were all covers so 3. Is there evidence	move septage: K Maintenan ecurely replaced? Y Yes C of tank leakage from a sept naged, cracked, or structura	□No tic, holding, pretr	eatment or pump	tank below the opera	iting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	•
er K	Septic/Holding Tank #1	☐ Yes 🔀 No	Yes No	☐ Yes 💆 No	
	Septic/Holding Tank #2	☐ Yes 🗷 No	☐ Yes ☑No	☐ Yes 🗗 No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1_ <i>1200</i>	s of septage were removed? gal Tank #2 <u></u>	gal Pretreatment	_		_
6. Location of septag	e disposal:	This Lan	d Applir	1	

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934