

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 7/20/17 Reason for Maintenance: Routine						
Property Address: 9651 83RD St. M. Property Owner's Name: anthony Hanson						
Municipality: ZIP: <u>55082</u> Property Identification Number:						
Maintenance Permit N	10: 99524m 10142	Maintainer Name a	nd License No. <u>Mey</u>	er Sewer Service, Ind	c./L915	
	0					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped Sludge and scum measured		II '	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
		-				
Do tanks need to be pumped?		= % Sludge & Sci				
☐ Yes ☐ No (if no provide measurements)						
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced? Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
evidence of dame		ally unsound main	terrance note cove			
	Tank	Leaking Out	Leaking In	Cover Damage		
		,	1	1		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	•	
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
	J		<i>/</i> .			
	Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes 🗖 No	☐ Yes ☐ No		
Tank #1 1000	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No Pes No Pes No Pers Real Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
Tank #1 1000	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Yes No Yes No Yes No Pes No Pes No Pers Real Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
Tank #1 1000	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No Pes No Pes No Pers Real Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
Tank #1 1000	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No Pes No Pes No Pers Real Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162