

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	12-4-17 Reason	for Maintenance:	Routine			
Property Address: 13	660 Paragon A	tue N F	Property Owner's N	ame: Barb (Chenowetch	
Municipality: 5+1/w	iter zip:550	8 乙 Property Idea	ntification Number	•		
Maintenance Permit No	: 650360	Maintainer Name ar	nd License No. <u>Smil</u>	ie's Sewer Service	e/L2428	
55°	330d.16a43			<u></u>		
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tan	ks NOT pumped)	
Tank(s) Pumped Sludge and scum measured		11 -	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to b	• •		= % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if n	o provide measurements)			'. '	3	
1. Access used to rem	ove septage: 🏚 Maintena	nce Hole 🗌 Other (e	enter authorization co	ode)		
3. Is there evidence o	urely replaced? Yes f tank leakage from a sep ged, cracked, or structur	otic, holding, pretr				
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🎾 No	☐ Yes (XINo	☐ Yes 🌠 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 1250	of septage were removed . gal Tank #2	_ gal Pretreatmen				
5. Other information:	List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or o	ther concerns.	
		ſ			 ,	
6. Location of septage	disposal:	etro Wa	ste			

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934