

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	11/3/17 Reason	n for Maintenance: _	Koutine			
Property Address:	175 M. JND.	St. F	roperty Owner's N	ame: Mancy	Kerley	
Municipality: Lake	land Shore AP: 550					
Maintenance Permit N	o: do20009150	Maintainer Name ar	d License No. <u>Mey</u>	er Sewer Service, In	c./L915	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
▼ Tank(s) Pumped     □ Sludge and scum measured			Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
Do tanks need to be pumped?		= % Sludge & Sci				
☐ Yes ☐ No (if	no provide measurements)	N 1	(0)-1414(1)-141	98V St.	1958	
1. Access used to ren	n <b>ove septage:</b> Maintena	ance Hole Other (e	nter authorization c	ode)		
2. Were all covers securely replaced?						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
evidence of damaged, cracked, or structurally unsound maintenance note covers:						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes XNo	☐ Yes \\\	☐ Yes X No		
	Septic/Holding Tank #2	☐ Yes (No	☐ Yes XNo	☐ Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	42				
	_ gal Tank #2 1000		: tankg	al Pump Tank	gal	
	: List any troubleshooting			5)		
Fence +	landscaptus o	ver top of	tanks	4" Standa	ipes	
6. Location of septage	//	P S+R	1	, , ,		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162