

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	10/31/17 Reason	for Maintenance: _	ROUTINE		
Property Address: 68	347 LAMAR AL	IE.S. F	roperty Owner's N	ame: ANDREW	POTHAN
Municipality: COTTA	AGE GROVE ZIP: 550	16 Property Ide	ntification Number:		
	: 1488d 9142 N				c./L915
	J				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
 ☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements) 		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintenar	nce Hole \square Other (e	enter authorization co	ode)	
2. Were all covers sec	curely replaced? Yes	□ No			
3. Is there evidence of evidence of dama	of tank leakage from a sep ged, cracked, or structura	tic, holding, pretr ally unsound main	eatment or pump tenance hole cove	tank below the opers?	erating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	□ Yes XNo	□ Yes ⊠No	□ Yes 🏚 No	
	Septic/Holding Tank #2	☐ Yes ☑No	☐ Yes 🗓 No	☐ Yes X No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1500	of septage were removed gal Tank #2 <u>JOGO</u> List any troubleshooting,	_gal Pretreatmen			
6. Location of septage	disposal:	P 5+	Paul		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162