

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| Date of Maintenance: | 11/17/17 Reason f | for Maintenance: | Routine | | |
|--|--|--|---------------------|----------------------|-----------------|
| Property Address: | | | | ame Helfred | Coughlin |
| Municipality: | Elmo ZIP:550 | The state of the s | | /) | 0 |
| | 0: <u>m6471p9190</u> M | | | | |
| Manrechance remire in | | arreamer Name ar | id Electise No. Mey | er sewer service, in | 2.7 1.7 1.3 |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped Sludge and scum measured | | Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| | | | | | |
| \square Yes \square No (if no provide measurements) | | | | | |
| 1. Access used to rem | nove septage: Maintenan | | | | |
| | curely replaced? Yes | | | , | |
| | | | eatment or pump | tank below the ope | rating depth or |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes 🗖 No | ☐ Yes ☑ No | ☐ Yes ☑ No | |
| | Septic/Holding Tank #2 | ☐ Yes 🗹 No | ☐ Yes ☐No | ☐ Yes ☐ No | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| Tank #1 1600 | of septage were removed? gal Tank #2 10000 List any troubleshooting, | gal Pretreatmen | 100 | 1184 | |
| Parameter and the second | | | | | |
| 6. Location of septage | disposal: | | | | |
| | | | | | |

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162