

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	manifectionice.	ROUTINE		
Property Address: 10620 NORWOOD	AVE N	Property Owner's N	ame: JOSEF TU	PECHINIAK
Municipality: STILLWATER TWSP ZIP: 5508	2 Property Ide	ntification Number:	:	
Maintenance Permit No: m8415a9209 Ma				c./L915
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
X Tank(s) Pumped	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or great			
Do tanks need to be pumped?				
\square Yes \square No (if no provide measurements)	, v staage a set		mo mase se pampea	in 25% of Greater
1. Access used to remove septage: Maintenance	e Hole Dother (e	enter authorization co	ode)	
2. Were all covers securely replaced? Yes	-			
Is there evidence of tank leakage from a septi evidence of damaged, cracked, or structurall		eatment or pump	tank below the ope	rating depth or
evidence of damaged, cracked, or structural	y unsound main	tenance hole cove	ers?	
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1		- 4	//	
300 30 100	☐ Yes ☐ No	☐ Yes ⊠No	☐ Yes 💆 No	
Septic/Holding Tank #2	☐ Yes INO	Yes ⋈ NoYes ⋈ No	☐ Yes ☑ No ☐ Yes ☑ No	
Septic/Holding Tank #2 Pretreatment Tank	· /	,	,	
	☐ Yes No	☐ Yes 🗖 No	☐ Yes ☑No	
Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☑No	☐ Yes ☐ No	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed?	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☑No ☐ Yes ☐No ☐ Yes ☐No	☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☐ No	gal
Pretreatment Tank Pump Tank	Yes No Yes No Yes No	☐ Yes ☑No ☐ Yes ☐No ☐ Yes ☐No ☐ tankg	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No al Pump Tank	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? Tank #1 1250 gal Tank #2	Yes No Yes No Yes No	☐ Yes ☑No ☐ Yes ☐No ☐ Yes ☐No ☐ tankg	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No al Pump Tank	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162