

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
<u>prior</u> to perform	ning maintenance activit	ies and remain on	-site for the durati	ion of the maintenar	ice activity.	
Date of Maintenance:	11/30/17 Reason	for Maintenance:	Routine		*	
Property Address: 52	60 Manning	ave. S. F	roperty Owner's N	ame: Robert	Retter	
Municipality: Aft			ntification Number:			
Maintenance Permit No:	m8625192371	Maintainer Name ar	d License No			
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
-	Tank	Leaking Out	Leaking In	Cover Damage		
5	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes KNo		
9	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons o	f septage were removed	?				
Tank #1 1500 gal Tank #2 gal Pretreatment tank gal Pump Tank					gal	
5. Other information:	List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.	
6. Location of septage of	disposal: W-					