

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 12/12/17 Reason for Maintenance: ROUTINE					
Property Address: /	1886 18 th ST	. N. F	Property Owner's N	ame: JEFF	OLSON
# ## ## ## ## ## ## ## ## ## ## ## ## #	LAKELANDZIP:550				
	0:W6405110177 N				 c./L915
Maniteriaries i similari		nameaner rame ar	ia zieense ner <u>iner</u>	er server service; m	SI/ <b>L</b> / · · · ·
Street Committee of the Street			The state of the s		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		// 5/4455			J. 2010 1. J. 2010 1.
1. Access used to remove septage: Maintenance Hole  Other (enter authorization code)					
2. Were all covers securely replaced? ✓ Yes □ No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	□ Yes 🗷 No	☐ Yes 💢 No	☐ Yes 🕅 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
A. Harrimanii gallana	of annianaau	2			
4. How many gallons of septage were removed?  Tank #1 1500 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
$\sim$ $\sim$ $\sim$ $\sim$ $\sim$ $\sim$ $\sim$ $\sim$					
6. Location of septage disposal: St Par					

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162