

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

		THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.		1 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete						
prior to perform	ming maintenance activiti	es and remain on-	site for the durati	on of the maintenanc	e activity.	
Date of Maintenance: 8/16/16 Reason for Maintenance: Rouline						
Property Address: 1689 Upper 15th St. S. Property Owner's Name: College Mc Donald						
					, -	
Municipality:	oix Beach ZIP: 550	3 Property Idea	itilication Number.			
Maintenance Permit No	o: <u>z 1362i 3554</u> n	Naintainer Name an	d License No. Meye	er Sewer Service/ L915		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintenar	nce Hole 🗌 Other (e	enter authorization co	ode)		
2. Were all covers securely replaced? 🗵 Yes 🗆 No						
3. Is there evidence of	of tank leakage from a sep aged, cracked, or structur	tic, holding, pretr	eatment or pump tenance hole cove	tank below the operars?	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes No	☐ Yes INo	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes INo	☐ Yes t No	☐ Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
	*		01			
6. Location of septage disposal: UTC 54. Paul						

Gode used by:

1199 Laward Are N

wit Lake Elmo