

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

				THE RESERVE AND DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO	
	completed in its entirety to				
-	ming maintenance activitie				nce activity.
Date of Maintenance:	10/14/16 Reason fo	or Maintenance: _	Routine)	
Property Address:	3500 KIMBRO	AUE.S. P	roperty Owner's Na	ame: JOEL	JENSEN
Municipality: COTTA	GE GROVE ZIP:5501	6 Property Iden	tification Number:		
	o: 0315254698 Ma				15
	ыратом сегазици такчина прукция картис.				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: Maintenand	ce Hole 🗌 Other (e	enter authorization co	ode)	
2. Were all covers se	curely replaced? 🔯 Yes 🗆	No			
3. Is there evidence	of tank leakage from a sept aged, cracked, or structura	ic, holding, pretr	eatment or pump tenance hole cove	tank below the ope ers?	erating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	- :
	Septic/Holding Tank #1	☐ Yes X No	☐ Yes ANo	Ŷes □ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	_
4. How many gallons	of septage were removed?				
			t tankg	gal Pump Tank	gal
5 Other information	: List any troubleshooting,				her concerns.
5. Other information	.,	10 00 000000	<u> </u>	7.000	
6. Location of septag	e disposal:	Stora	<i>y</i>		
	3*			Code used	Wu:
				Code uscal 2007 bakque	n Ave.N
				W. Lakelar	rd
,	Maintenance activities m	ust be reported	to the Departm		
		1070			