

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its ent	irety to constitute a valid maintenance permit. This permit must be completed
prior to performing maintenance a	ctivities and remain on-site for the duration of the maintenance activity.
	eason for Maintenance: Routine
Property Address: 13295 St Choi	X TIL N Property Owner's Name: Connie Sugden
	55082 Property Identification Number:
Maintenance Permit No: <u>U7977 N 8499</u>	
The state of the s	Maintainer Name and License No. Pinky's Environmental Sewer Service/ L1673
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)
Tank(s) Pumped	Liquid Level of Tank — in
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100
\square Yes \square No (if no provide measureme	
1. Access used to remove septage: Mair	intenance Hole Other (enter authorization code) In I massay is Longeston
2. Were all covers securely replaced? \Box	Yes \(\sum \text{No} \)
3. Is there evidence of tank leakage from a	a septic, holding, pretreatment or pump tank below the operating depth or
evidence of damaged, cracked, or stru	icturally unsound maintenance hole covers? Yes No
Tank	Leaking Out Leaking In Cover Damage
Septic/Holding Tank #1	☐ Yes ☐ No ☐ Yes ☐ No
Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No
Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No
Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No
4. How many gallons of septage were remo	oved?
Tank #1 <u>/ Z 555</u> gal Tank #2	gal Pretreatment tankgal Pump Tankgal
Other information: List any troubleshoo	ting, minor repairs conducted, tank safety concerns, or other concerns.
6. Location of septage disposal:	57/2
Pi	inky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673