

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be comp	leted in its entirety to maintenance activities				
Date of Maintenance: 9-		r Maintenance:	cont	ine	
Alla		1		Duane	Saust
Property Address:	A		operty Owner's Name	e: Dunne	parell
Municipality: Stillu	TIP: 5508	Property Ident	ification Number:		_
Maintenance Permit No: <u>M</u>	220968496 Ma	intainer Name and	License No. Pinky's	Environmental Sew	er Service/ L1673
					0.7
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☐ Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? ☐ Yes ☐ No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? ☐ Yes ☐ No 					
	Tank	Leaking Out	Leaking In	Cover Damage	
Sept	ic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	*
Sept	cic/Holding Tank #2	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No	
Pret	reatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pum	np Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed? Tank #1 175 gal Tank #2 gal Pretreatment tank gal Pump Tank gal 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
6. Location of septage disp	posal:5	RA			
Pinky's Environmental Sewer Service Inc.					

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673