

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit r	nust be complete	
prior to perfo	rming maintenance activit	ies and remain on	-site for the durati	on of the maintenar	nce activity.	
Date of Maintenance:	9-19-17 Reason	for Maintenance:	Rautir	W.		
Property Address:	8 Bichner Lar	10	Property Owner's Na	ame: Levoy Si	pangler	
Municipality: Mahd			ntification Number:		,	
Maintenance Permit N	10: <u>e776497963</u>				wer Service/ L167	
	7					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	curely replaced?  Yes of tank leakage from a sep aged, cracked, or structur	otic, holding, preti			ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 /200	gal Tank #2 800	_gal Pretreatmen	tankga	al Pump Tank	gal	
	: List any troubleshooting			ty concerns, or othe		
					V - W	
6. Location of septage	e disposal:					

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673