

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
<u>prior</u> to performing ma	intenance activiti	es and remain on	-site for the durat	tion of the maintena	nce activity.
Date of Maintenance: $9/5$	117 Reason	for Maintenance:	Routine)	
Property Address: 9055	Treey	Cloude	roperty Owner's N	lame: Forrest (Maylor!
Municipality:	uflowed 5	7/Property Ide	ntification Number	1	
Maintenance Permit No: <u>v の</u> ち	21X8151 N	aintainer Name ar	nd License No. <u>Mi</u>	EYER/L915	
Maintenance Perfo	ormed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove sept Were all covers securely re 	Renal 6		enter authorization c	ode)	
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
-	Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Ho	olding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Ho	olding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatn	nent Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tai	nk	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septag	e were removed?				
Tank #1 750 gal Tank #2 750 gal Pretreatment tank gal Pump Tank					gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
old cers pools					
6. Location of septage disposal:					