

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: $8/1/17$ Reason	n for Maintenance:	ROUTINE			
Property Address: 1226 NOLAN A	AVE. N. F	Property Owner's N	ame: <u>STEPHAN</u>	IE MOENCH	
Municipality: WESTLAKELAND ZIP: 550	28) Property Ide	ntification Number:			
Maintenance Permit No: <u>d0087m7356</u>	Maintainer Name ar	nd License No. <u>Mey</u> e	er Sewer Service, Inc	./L915	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
✓ Tank(s) Pumped	'	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
Sludge and scum measured	-				
Do tanks need to be pumped?	= % Sludge & Sci				
☐ Yes ☐ No (if no provide measurements	)				
1. Access used to remove septage:   Mainten	ance Hole Other (e	enter authorization co	ode)		
2. Were all covers securely replaced?  Yes	□No	•			
	eptic, holding, preti	reatment or pump	tank below the oper	rating depth or	
Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu	eptic, holding, preti rally unsound main	reatment or pump tenance hole cove	tank below the oper	rating depth or	
	eptic, holding, preti rally unsound main Leaking Out	teatment or pump tenance hole cove	tank below the operrs?  Cover Damage	rating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu				rating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu	Leaking Out	Leaking In	Cover Damage	rating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu  Tank  Septic/Holding Tank #1	Leaking Out	Leaking In  ☐ Yes ☐ No	Cover Damage  Yes No	rating depth or	
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2	Leaking Out  Yes No Yes No	Leaking In  Yes No Yes No	Cover Damage  Yes No Yes No	rating depth or	
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No		
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed gallons and many gallons and many gallons are septage were removed to the septage were removed to	Leaking Out  Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Yes No	gal	
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed gal Tank #2  5. Other information: List any troubleshooting	Leaking Out  Yes No Yes No Yes No Yes No Yes No gal Pretreatmen	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Yes No	gal	
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed gallons and many gallons and many gallons are septage were removed to the septage were removed to	Leaking Out  Yes No Yes No Yes No Yes No Yes No gal Pretreatmen	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No Yes No	gal	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162