

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	8/14/17 Reason					
Property Address: 2	470 REDWIN	IG AVE.S. F	roperty Owner's N	ame: DAVE 1	PELSON	
	ARUS PT. ZIP:	Property Ide				
Maintenance Permit N	o: C7600n7389	—— Maintainer Name ar	nd License No. Mey	er Sewer Service, Ind	c./L915	
Maintenance Performed ☐ Tank(s) Pumped ☐ Sludge and scum measured			Tank Measurement (must be completed if tanks NOT pumped)			
		11 .	Liquid Level of Tank in Sludge Level in Tank in Sludge + Scum / Liquid Level X 100			
		11 -				
Do tanks need to be pumped? — Yes — No (if no provide measurements)		= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
	no provide measurements	<u></u>				
1. Access used to rem	nove septage: Mainten	ance Hole 🗀 Other (e	enter authorization co	ode)		
	curely replaced? 🖊 Yes					
3. Is there evidence of dama	of tank leakage/from a se aged, cracked, or structu	ptic, holding, pretr	eatment or pump tenance hole cove	tank below the opers?	erating depth or	
						
					1	
	Tank	Leaking Out	Leaking In	Cover Damage]	
	Tank Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage Yes No		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑No	☐ Yes ☐ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐ No		
4 How many gallons	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No d?	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
Tank #1 <u>/ 660</u>	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	☐ Yes ☐ No ☐ d? _ gal Pretreatmen	☐ Yes ☐ No	☐ Yes ☐ No	gal	
Tank #1 <u>/ 660</u>	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2 /060	☐ Yes ☐ No ☐ d? _ gal Pretreatmen	☐ Yes ☐ No	☐ Yes ☐ No	gal	
Tank #1 <u> </u>	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2 /060 List any troubleshooting	☐ Yes ☐ No ☐ d? _ gal Pretreatmen	☐ Yes ☐ No	☐ Yes ☐ No	gal	
Tank #1 <u>/ 660</u>	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2 /060 List any troubleshooting	☐ Yes ☐ No ☐ d? _ gal Pretreatmen	☐ Yes ☐ No	☐ Yes ☐ No	gal	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162