

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	NINTER THE TOTAL CONTRACTOR OF			engani adapa antangkaga sideora (ili)		
Maintenance Performed			Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured		N 2	Tank in	Scum Level in Tank	in	
Do tanks need to be pumped? — Yes — No (if no provide measurements)		= % Sludge & Scu	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if	no provide measurements)				
		and the second of	2007 4704AN 10.50 0.50 0.70 0.70	1.		
1. Access used to rea	nove septage: Mainten	ance Hole 🗀 Other (e	enter authorization co	ode)		
			enter authorization co	ode)		
2. Were all covers se	curely replaced? 🖊 Yes	□No			rating depth or	
2. Were all covers se		□No			rating depth or	
2. Were all covers se	curely replaced? 🖊 Yes	□No			rating depth or	
2. Were all covers se	ecurely replaced? Z Yes of tank leakage from a se aged, cracked, or structu	□ No ptic, holding, pretr rally unsound main	reatment or pump tenance hole cove	tank below the ope rs?	rating depth or	
2. Were all covers se	ocurely replaced? Z Yes of tank leakage from a se aged, cracked, or structu	No ptic, holding, pretrally unsound main	reatment or pump tenance hole cove Leaking In	tank below the ope rs? Cover Damage	rating depth or	
2. Were all covers se	curely replaced? Z Yes of tank leakage from a se aged, cracked, or structu Tank Septic/Holding Tank #1	No Poptic, holding, pretrally unsound main Leaking Out Yes No	Leaking In	Cover Damage Yes No	rating depth or	
2. Were all covers se	curely replaced? Z Yes of tank leakage from a se aged, cracked, or structu Tank Septic/Holding Tank #1 Septic/Holding Tank #2	No Pptic, holding, pretrally unsound main Leaking Out Yes No Yes No	Leaking In Yes No	Cover Damage Yes No	rating depth or	
Were all covers set Is there evidence evidence of dam 4. How many gallons	Tank Septic/Holding Tank #2 Pretreatment Tank	No Potic, holding, pretrally unsound main Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	tank below the operrs? Cover Damage Yes No Yes No Yes No Yes No		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162