

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 8/18/17 Reason	n for Maintenance:	ROUTINE			
Property Address: 9457 NORELL AVE N Property Owner's Name: GREG PETERSON					
Municipality: STILLWATER TUSP ZIP: 55082 Property Identification Number:					
Maintenance Permit No: <u>17603 u 739 7</u> Maintainer Name and License No. <u>Meyer Sewer Service</u> , Inc./L915					
Maintenance Permit No: 17/005 W 1311	Maintainer Name an	d License No. Mey	of Sewer Service, inc.	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
evidence of damaged, crueical, or as acts				*	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes 🗖 No	☐ Yes 🎵 No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes 🖊 No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?					
Tank #1 1250 gal Tank #2 1350 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Junel through 4" pipes munholes under Plants					
6. Location of septage disposal:					

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162