

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

THIS SCHOOL HIGSE DE	completed in its entirety of	o constitute a vali	id maintenance pe	rmit. This permit mu	ist de completed
prior to perfor	ming maintenance activitie	s and remain on-	site for the duration	n of the maintenanc	e activity.
Date of Maintenance:	8/24/17 Reason f 246 113th St. S	or Maintenance: _	Routine)		
Property Address: &	246 113th St. S	P	roperty Owner's Na	me: Martin	Lynch
thusisinglitus Cott	acq Showezip: 550	V/ Property Iden	tification Number:	.	<i>*</i>
municipatity. Cocc	acque Suoven Os	Jan Operey Iden			
Maintenance Permit N	0: W7384/10203 M	aintainer Name an	d License No. Meye	r Sewer Service/ L913	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)
☐ Sludge and scum measured		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
4 4	nove septage: Maintenan	sa Hola 🕅 Other (e	enter authorization co	de)	
			ancer agenorization co		
2. Were all covers se	curely replaced? Yes	⊥NO ki boldina protr	costmont or pump	tank helow the onera	ting death or
3. Is there evidence evidence of dam	of tank leakage from a septaged, cracked, or structura	illy unsound main	tenance hole cove	rs?	cing acpen of
	- ·				
	Tank	Leaking Out	Leaking In	Cover Damage	
	· · · · · · · · · · · · · · · · · · ·	Leaking Out		Cover Damage ☐ Yes ☐ No	
	Tank		Leaking In		
	Tank Septic/Holding Tank #1	☐ Yes 🔀 No	Leaking In ☐ Yes ☐ No	☐ Yes ☐ No	
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes 🗖 No	Leaking In Yes No Yes No	☐ Yes ☐ No	
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank s of septage were removed	☐ Yes 🔀 No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	Leaking In Yes No Yes No Yes No Yes No	☐ Yes ☐ No	
Tank #1 150 0	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes 🔀 No ☐ Yes ☐ Ro	Leaking In Yes No Yes No Yes No Yes No Yes No	☐ Yes ☐ No	gal
Tank #1 150 0	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes 🔀 No ☐ Yes ☐ Ro	Leaking In Yes No Yes No Yes No Yes No Yes No	☐ Yes ☐ No	gal
Tank #1 150 0	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank s of septage were removed	☐ Yes 🔀 No ☐ Yes ☐ Ro	Leaking In Yes No Yes No Yes No Yes No Yes No	☐ Yes ☐ No	gal
Tank #1 150 0	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes 🔀 No ☐ Yes ☐ Ro	Leaking In Yes No Yes No Yes No Yes No Yes No	☐ Yes ☐ No	gal