

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	<i>8/24/17</i> Reason	for Maintenance: .	ROUTINE								
Property Address: <u>8</u>	483 27th ST.	<i>N</i> i	Property Owner's N	ame: SHANE	WEIS						
Municipality: LAKE	ELMO ZIP: 550	<u>4</u> 2 Property Ide	ntification Number:								
Maintenance Permit No	: V1797n8116 N	Naintainer Name ai	nd License No. <u>Meye</u>	er Sewer Service, Ind	/L915						
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)									
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater									
						☐ Yes ☐ No (if r	no provide measurements)				-
						1. Access used to rem	ove septage: 🗓 Maintenar	nce Hole 🗌 Other (enter authorization co	ode)	
2. Were all covers sec	curely replaced? 🔀 Yes	□ No									
			reatment or numn	tank below the one	rating depth or						
3. 13 tilele evidelice o	i talik teakage irolli a sep	cic, notains, prec	teres as belo some		annia arkan a						
evidence of dama	of tank leakage from a sep ged, cracked, or structura	ally unsound main	tenance hole cove	rs?							
evidence of dama	ged, cracked, or structure	Leaking Out	tenance hole cove	Cover Damage							
evidence of dama											
evidence of dama	Tank	Leaking Out	Leaking In	Cover Damage							
evidence of dama	Tank Septic/Holding Tank #1	Leaking Out	Leaking In Yes Lino	Cover Damage Yes KNo							
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes No							
4. How many gallons of Tank #1 <u> </u>	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes Ho Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Pes No	gal						

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162